

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, October 24, 2023	Project Contact:	Brian Clauto
Spread G: Giles	Sta 10600-10605, 10510-10523, 11297-11354 ATWS 340, 610, 610A, 610B, 1124, 1125 AR GI234, 353.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	☐ Tree Felling		☐ Clearing/Grubbing			Grading [		Trenching		Strir	nging/Welding	
$\boxtimes$	Lowering/E	wering/Backfilling		Final Grad	ling		Temp. Stabilization		Perm. Stabilization	$\boxtimes$	Resource Crossing	
										Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?									$\boxtimes$			
	2.									$\boxtimes$		
	3.	Areas of of	fsite	sediment de	position ob	serve	d?				$\boxtimes$	
■ Comments: Inspected the following resources: S-S5, S-Q13, S-NN12, S-NN11												
Routine Maintenance: ( <u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, October 24, 2023



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

Date: Tuesday, October 24, 2023





Figure 3: Sta11297, ECD's are in place.



Figure 4: Designated crossing S-NN12, ECD's are in place.