

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew G	Matthew Grant			
Inspection Date:	Monday, November 27, 2023	Project Contact:	Brian Clauto				
Spread G: Giles	Sta 11158+68-11172, 10965-10900, 10927+63-10930 ATWS 471 AR GI 249.03, 242.01	Weather:	Dry				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)							
Tree Felling	🗌 Clearing/Grubbing 🛛 🖾 Gra	ding 🛛 Trenching		$\boxtimes$	Stringing/Welding		
🛛 Lowering/Backfilling 🗌 Final Grading 🗌 Temp. Stabilization 🗍 Perm. Stabilizatio		Stabilization	$\boxtimes$	Resource Crossing			
				Yes	No	N/A	
1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?				$\boxtimes$			
2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?				$\boxtimes$			
3. Areas of offsite sediment deposition observed?					$\boxtimes$		
<ul> <li><u>Comments:</u> Inspected the following resources: S-NN17, S-EF24, S-EF25, S-MN11, S-Y3, S-Y2</li> <li>Routine Maintenance: (<u>72-Hour Deadline</u> from Notification)         <ul> <li>N/A</li> </ul> </li> <li>Ineffective Controls: (<u>24-Hour Deadline</u> from Notification)             <ul> <li>N/A</li> </ul> </li> <li>Recommended Corrective Action: N/A</li> </ul>							

## Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, November 27, 2023



## FIELD INSPECTION PHOTO LOG

