

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Thursday, January 4, 2024	Project Contact:	Brian Clauto		
Spread G: Montgomery Giles	Sta 11159+31-11165, 11255- 11254+57, 11600-11614+74 ATWS1369, 1464, 1373 AR GI 249.03, 253.03, MN258.03	Weather:	Wet		

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
☐ Tree Felling		☐ Clearing/Grubbing		$\boxtimes$	Grading 🗵 Trenching		Trenching	$\boxtimes$	Stringing/Welding				
	Lowering/Backfilling			Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Reso		ource Crossing		
									Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							$\boxtimes$						
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$				
	3.	Areas of of	fsite :	sediment deposition o	bserve	d?				$\boxtimes$			
■ Comments: Inspected the following resources: S-NN17, S-RR2, W-RR1B, S-006, S-RR14, S-RR13													
Routine Maintenance: ( <u>72-Hour Deadline</u> from Notification) - N/A													
Ineffective Controls: (24-Hour Deadline from Notification) - N/A													
Recommended Corrective Action: N/A													

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, January 4, 2024



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Thursday, January 4, 2024

Figure 1: Sta11163+64, ECD's are in place.



Figure 2: Designated crossing S-NN17. ECD's are in place.



Figure 3: Sta 11254+57, ECD's are in place.



Figure 4: Sta 11614+74, ECD's are in place.

