

## COMPLAINT INVESTIGATION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, February 16, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12866+36 – 12890+00	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |  |  |   |  |  |
|--|--|---|--|--|
| <input type="checkbox"/> Tree Felling                    | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant           |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Background:** This investigation was conducted in response to a complaint (IR#: 312695) submitted to PREP on February 14, 2024. The incident description is “sediment in stream S-IJ12 MVP mile 244” at “MVP mile 244 S-IJ13”.

**Observations:**

1. Crews are active in this area lowering in pipe and grading following install.
2. Dewatering operations are occurring to remove groundwater from the trench. Two dewatering structures are located adjacent to Stream S-IJ12.
3. Controls observed during this inspection were installed and functioning properly.
4. No impacts to resources were found.
5. No sediment discharged off ROW was found during the inspection.

**Comments:** ROW inspected in Roanoke County from STA 12866+36 though STA 12890+00. The following resources were documented during the onsite complaint investigation: S-EF46, S-ST9b, W-KL48, W-KL49, W-KL51, S-KL55, W-MN7 and S-IJ12.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Friday, February 16, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, February 16, 2024

**Figure 1: STA 12893+00** – Dewatering structure #1 installed and functioning properly.

☉ 209°SW (T) ● 37.148882°N, 80.134095°W ±16ft ▲ 2642ft



**Figure 2: STA 12893+00** – Dewatering structure #1 installed and functioning properly.

☉ 296°NW (T) ● 37.148682°N, 80.134059°W ±13ft ▲ 2628ft



**Figure 3: STA 12893+00** – Dewatering structure #2 installed and functioning properly.

☉ 159°S (T) ● 37.148688°N, 80.134086°W ±13ft ▲ 2632ft



**Figure 4: Stream S-IJ12** – Looking upstream at S-IJ12 from temp. equipment crossing at both dewatering structures. No impacts to resource identified.

☉ 335°NW (T) ● 37.148376°N, 80.134016°W ±9ft ▲ 2621ft

