

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, February 26, 2024	Project Contact:	Brian Clauto
Spread G: Giles	Sta 10512-10514+60, 10600, 11023+80, 11026-11015+58 ATWS 610, 610A, 1145, 1146 AR GI 244, 234	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling			☐ Clearing/Grubbing ☐		Grading	\boxtimes	Trenching		Strii	nging/Welding		
\boxtimes	Lowering/E	Backfilling	ekfilling 🔲 Final Grading 🔲 Temp. Stabilization 🔲 Perm. Stabilizati		Perm. Stabilization	ı 🗆	Res	ource Crossing				
									Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
	3.	Areas of o	ffsite	sediment deposition	observe	d?				\boxtimes		
■ Comments: Inspected the following resources: S-Q12, S-IJ18, S-RR5												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												
											_	

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ____

Date: Monday, February 26, 2024



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, February 26, 2024

Figure 1: Designated stream S-Q12, ESC is in place.



Figure 2: Designated stream S-IJ18, ESC is in place.



Figure 3: Designated stream S-RR5, ESC is in place.



Figure 4: Sta 11020, area is stabilized and ESC is in place.

