

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, March 25, 2024	Project Contact:	Brian Clauto
Spread G: Giles	Sta11230+70-11158+68 ATWS 1370, 1370A, 1347, 1464, 1369 AR MLV25, GI249.01, 249.02, 249.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	☐ Tree Felling			☐ Clearing/Grubbing ☐ Grading ☐			Trenching		Stri	nging/Welding			
	Lowering/B	ng/Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Dorm		mant		
									Yes	No	N/A		
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes				
	3.	Areas of of	fsite	sediment deposition ol	oserve	d?				\boxtimes			
■ <u>Comments:</u> Inspected the following resources: S-NN17													
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A													
Ineffective Controls: (24-Hour Deadline from Notification) - N/A													
Recommended Corrective Action: N/A													

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, March 25, 2024



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 25, 2024

Figure 1: Designated crossing S-NN17, stabilization and ESC are in place.



Figure 2: ATWS 1369, stabilization and ESC are in place.



• <u>Figure 3:</u> Sta 11176, ESC and permanent style waterbars are in place.



<u>Figure 4</u>: Sta 11195, ESC and permanent style waterbars are in place.

