

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, April 16, 2024	Project Contact:	Brian Clauto
Spread G: Montgomery	Sta 11670-11767+26 AR MLV 26	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Resource Crossing

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

▪ **Comments:** Inspected the following resources: S-MN21, S-MN22, S-EF65, S-EF62, S-IJ52, W-IJ46

Routine Maintenance: (*72-Hour Deadline from Notification*)

- Sta 11690-11688+35, repair rill and restabilize.
- MVP MLV 26 repair rill and re stabilize.

Ineffective Controls: (*24-Hour Deadline from Notification*)

- N/A

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, April 16, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 16, 2024

- Figure 1: Sta 11688+35, area lacks adequate stabilization and is showing signs of rill erosion.



- Figure 2: Sta 11690, area lacks adequate stabilization.



- Figure 3: MVP MLV 26 station, rear of pad area is showing signs rill erosion.



- Figure 4: Sta 11670, area is stabilized and ESC is in place.

