

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, June 4, 2024	<b>Project Contact:</b>	Brian Clauto
<b>Spread G: Giles</b>	Sta 11767+44, 11670-11680, 11158-11158+68, 11040-11020, 11254, 11614+20-11600 ATWS 1145, 1146, AR GI 244, 258.04	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |   |  |   |   |
|---|---|--|---|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing        | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching                      | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Grading | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

▪ **Comments:** Inspected the following resources: S-IJ52, S-IJ18, S-RR13, S-006, S-RR14

**Routine Maintenance:** *(72-Hour Deadline from Notification)*

- Sta 11675 rill erosion requires repair and re stabilized.

**Ineffective Controls:** *(24-Hour Deadline from Notification)*

- N/A

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_  \_\_\_\_\_

**Date:** Tuesday, June 4, 2024

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, June 4, 2024

Figure 1: Sta 11040, final grading is being constructed.



Figure 2: Designated crossing S-006, ESC is in place.



Figure 3: Sta 11680, ESC is in place.



Figure 4: Sta 11675, approximately 30ft of erosion requires repair and re stabilized.

