

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, June 25, 2024	Project Contact:	Brian Clauto
Spread G: Giles	Sta 11156+80-11158, 10700-10690 ATWS 1391, 1390, 816 AR GI 241.04	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	☐ Tree Felling		☐ Clearing/Grubbing		\boxtimes	Grading		Trenching		Strir	nging/Welding		
	Lowering/E	3ackfilling ☐ Final Gra		Final Grading		Temp. Stabilization		Perm. Stabilization	\boxtimes	Dormant			
									Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes					
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?											
	3.	Areas of of	fsite	sediment deposition o	bserve	d?				\boxtimes			
■ <u>Comments:</u> Inspected the following resources: S-G32, S-G33													
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A													
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A													
Recommended Corrective Action: N/A													

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, June 25, 2024

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Tuesday, June 25, 2024

Figure 1: Designated crossing S-G33, ESC is in place.



■ Figure 2: Designated crossing S-G32, ESC is in place.



Figure 3: Sta 1156+80, ESC is in place.



■ Figure 4: Sta 10690, ESC is in place.

