

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, June 25, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11150+00 – 11160+00 STA 11053+00 – 11064+00 STA 10920+00 – 10929+71 MVP-GI-245.01 MVP-GI-249 MVP-MLV-AR-25	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN17, S-Y3 and S-Y2.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, June 25, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 25, 2024

Figure 1: MLV-AR-25 – Controls in place and functioning properly.

☉ 25°NE (T) ● 37.316345°N, 80.544948°W ±13ft ▲ 2194ft



Figure 2: STA 11053+00 – Controls in place and functioning properly.

☉ 274°W (T) ● 37.317956°N, 80.546841°W ±13ft ▲ 2188ft



Figure 3: STA 11065+00 – Controls in place and functioning properly.

☉ 305°NW (T) ● 37.315180°N, 80.544095°W ±62ft ▲ 2067ft



Figure 4: STA 10926+00 – Controls in place and functioning properly.

☉ 341°N (T) ● 37.331988°N, 80.583540°W ±16ft ▲ 2132ft

