

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, August 13, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County Montgomery County</b>	STA 11765+00 – 11788+00 STA 11976+00 – 11988+00 MVP-GI-241.01/.04 MVP-MN-266	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ52 and W-IJ46-PEM.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Thursday, August 13, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, August 13, 2020

**Figure 1: MVP-GI-241.04** – Controls in place and functioning properly.

☉ 174°S (T) ● 37°21'5"N, 80°38'58"W ±16ft ▲ 2173ft



**Figure 2: STA 11769+00** – Controls in place and functioning properly. Area stabilized with straw.

☉ 72°E (T) ● 37°17'46"N, 80°22'2"W ±98ft ▲ 2011ft



**Figure 3: STA 11978+00** – Controls in place and functioning properly.

☉ 320°NW (T) ● 37°16'11"N, 80°19'22"W ±16ft ▲ 1703ft



**Figure 4: STA 11987+00** – Controls in place and functioning properly.

☉ 288°W (T) ● 37°16'6"N, 80°19'14"W ±16ft ▲ 1646ft

