

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, August 10, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10929+71 – 11011+87 MVP-GI-243.01 ATWS 974/974A/1137/1138/467	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-RR4, S-E24 and S-E25.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, August 10, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, August 10, 2020

Figure 1: STA 11012+00 – Controls in place and functioning properly.

☉ 115°SE (T) ● 37°16'44"N, 80°38'40"W ±42653ft ▲ 2529ft



11012

Figure 2: STA 10985+00 – Controls in place and functioning properly.

☉ 118°SE (T) ● 37°19'33"N, 80°33'55"W ±16ft ▲ 2370ft



10985

Figure 3: STA 10970+00 – Controls in place and functioning properly.

☉ 301°NW (T) ● 37°19'38"N, 80°34'14"W ±32ft ▲ 2411ft



10970

Figure 4: STA 10941+00 – Controls in place and functioning properly.

☉ 114°SE (T) ● 37°19'47"N, 80°34'45"W ±16ft ▲ 2262ft



10941