

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Tuesday, August 4, 2020	Project Contact:	Brian Clauto		
Spread G: Giles Montgomery	AR-GI-244 MP208.6- 206.7 ATWS 1138, 1137, 1487 MP 223.1, 223	Weather:	Dry		

Montgomery		ATWS 1138, 1137, 1487 MP 223.1, 223	weather.	Dry	ыу					
	ACTIVE STAG	E OF CONSTRUCTION: (Che	eck all that	apply)						
	Tree Felling	☐ Clearing/Grubbing	☐ Gra	ding		Trenching		Stri	nging/Welding	
	Lowering/Backfilling	☐ Final Grading	☐ Tem	mp. Stabilization	☐ Perm.	Perm. Stabilization	\boxtimes	Dormant		
	sediment Are all co	rols installed and implemented t control plan and stormwater n ontrol measures properly maint	manageme	nt plans? fective operating	conditi	on in accordance	Yes	No	N/A	
	with good	d engineering practices and, w offsite sediment deposition ob		able, manufactur	er spe	cifications?		\boxtimes		
 Comments: Inspected the following resources: S-IJ18, S-RR5, S-E20, S-Y2, S-Y3 S-E25, S-E24, W-IJ46, S-IJ52 ECD's were in place at the crossing. Routine Maintenance: (72-Hour Deadline from Notification) N/A Ineffective Controls: (24-Hour Deadline from Notification) N/A Recommended Corrective Action: N/A 										
	The recommende condition(s) curre	al/A ed corrective action deadline date a cently constitute non-compliance and assued to the entity responsible for expanding the constitute of the entity responsible for expanding the constitute.	d/or corrective	e actions are not c	omplete	ed by the deadline, oth				

Date: Tuesday, August 4, 2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 4, 2020






Figure 2: Designated crossing S-E25, controls in place.



Figure 3: Designated stream S-Y3, controls in place.



- Figure 4: Near MP223, area is stabilized.

