

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, July 31, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11596+94 – 11618+91 ATWS 1373/1057 MVP-MN-258.04/.03 Laydown Yard 028	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-OO6, S-RR13 and S-RR14.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, July 31, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, July 31, 2020

Figure 1: Laydown Yard 028 – Leak protection in place and functioning properly.

☉ 101°E (T) ☉ 37°20'9"N, 80°48'29"W ±16ft ▲ 1566ft



Figure 2: Stream S-RR13 – Controls in place and functioning properly around Craig Creek crossing of MVP-MN-258.04.

☉ 172°S (T) ☉ 37°18'52"N, 80°24'9"W ±16ft ▲ 1914ft



Figure 3: STA 11618+00 – Controls in place and functioning properly.

☉ 74°E (T) ☉ 37°18'49"N, 80°24'5"W ±2349ft ▲ 1945ft



Figure 4: Stream S-006 – Controls in place and functioning properly around Craig Creek crossing.

☉ 286°W (T) ☉ 37°18'49"N, 80°24'16"W ±16ft ▲ 1940ft

