

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 26, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11669+08 – 11788+43	Weather:	Dry

	ACTIVE STAGE	EOF CONSTRUCTION: (Ch	neck all that apply)							
	Tree Felling	☐ Clearing/Grubbing	☐ Grading	☐ Trenching		Stri	inging/Welding			
	Lowering/Backfilling	☐ Final Restoration	☐ Temp. Stabilization	on Perm. Stabilization	on 🗵 Dormant					
					Yes	No	N/A			
		ols installed and implemented control plan and stormwater		approved erosion and	\boxtimes					
		ntrol measures properly mair engineering practices and, v			\boxtimes					
	· ·	offsite sediment deposition of		·		\boxtimes				
	<u>Comments:</u> Inspected the following resources: S-MN21, S-MN22, S-EF65, S-EF62, S-IJ52 and W-IJ46-PEM. PPL crews installing fencing and cattle gates at several locations along the ROW. Crews also repairing ESC controls and re-stabilizing ROW.									
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.										
	Inspector Sign	nature: Machael	l Willis							
	Date: Wedn	esday, August 26, 2020								



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 26, 2020

<u>Figure 1</u>: **STA 11675+00** – Crews actively re-stabilizing with seed and straw.



<u>Figure 2</u>: **Stream S-MN22** – Controls in place and functioning properly around S-MN22 crossing.



Figure 3: **STA 11765+00** – Fencing and gate installed. Crews actively stabilizing with seed and straw.



Figure 4: STA 11792+00 – Fencing and gate installed.

