

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, October 1, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	Laydown Yard 026	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_



**Date:** Thursday, October 1, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, October 1, 2020

**Figure 1: Laydown Yard 026** – Controls in place and functioning properly.

☉ 252°W (T) ● 37°19'7"N, 80°39'29"W ±16ft ▲ 1787ft



**Figure 2: Laydown Yard 026** – Secondary containment in place and functioning properly.

☉ 86°E (T) ● 37°19'7"N, 80°39'27"W ±16ft ▲ 1793ft



**Figure 3: Laydown Yard 026** – Secondary containment in place and functioning properly.

☉ 104°E (T) ● 37°19'6"N, 80°39'24"W ±16ft ▲ 1789ft



**Figure 4: Laydown Yard 026** – Controls in place and functioning properly.

☉ 86°E (T) ● 37°19'5"N, 80°39'33"W ±98ft ▲ 1756ft

