

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, September 29, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County Montgomery County</b>	STA 11163+00 – 11177+00 STA 11020+00 – 11030+00 STA 11762+54 – 11770+00	<b>Weather:</b>	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ18, S-IJ19, S-IJ52 and W-IJ46-PFO.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Tuesday, September 29, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, September 29, 2020

**Figure 1: STA 11176+00** – Controls in place and functioning properly.

☉ 111°E (T) ● 37°18'31"N, 80°30'51"W ±16ft ▲ 1884ft



11176

**Figure 2: Stream S-IJ18** – Controls in place and functioning properly around stream S-IJ18 crossing.

☉ 176°S (T) ● 37°19'18"N, 80°33'10"W ±13051ft ▲ 2339ft



S-IJ18

**Figure 3: STA 11020+00** – Controls in place and functioning properly.

☉ 304°NW (T) ● 37°19'23"N, 80°33'14"W ±16ft ▲ 2461ft



11020

**Figure 4: STA 11765+00** – Controls in place and functioning properly. Area stabilized with straw.

☉ 336°NW (T) ● 37°17'45"N, 80°22'4"W ±32ft ▲ 2008ft



11765