

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, November 6, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Montgomery County</b>	STA 11929+42 – 12008+53 MVP-MN-266	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: W-NN6 and S-G36.

**Routine Maintenance:** (72-Hour Deadline from Notification)

- STA 11950+00: P1 maintenance needed.
- STA 11962+50: P1 maintenance needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** **Friday, November 6, 2020**

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, November 6, 2020

**Figure 1: STA 11938+00** – Controls in place and functioning properly.

☉ 160°S (T) ● 37°16'47"N, 80°19'41"W ±32ft ▲ 2289ft



11938

**Figure 2: STA 11950+00** – P1 maintenance needed.

☉ 224°SW (T) ● 37°16'6"N, 80°19'0"W ±5955ft ▲ 2166ft



SSF

11950

**Figure 3: STA 11962+50** – P1 maintenance needed.

☉ 20°N (T) ● 37°16'25"N, 80°19'30"W ±32ft ▲ 1914ft



11962+50

**Figure 4: STA 11990+00** – Controls in place and functioning properly.

☉ 87°E (T) ● 37°16'3"N, 80°19'11"W ±16ft ▲ 1624ft



11990