

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Wednesday, October 28, 2020	Project Contact:	Brian Clauto		
Spread G: Montgomery	AR 258.02 MP 219.59 ATWS 1057, 1373	Weather:	Rainy		

		AIVV.	3 1037, 1373								
	ACTIVE STAG	E OF (	CONSTRUCTION: (C	heck al	I that apply)						
	Tree Felling		Clearing/Grubbing		Grading		Trenching		Stri	inging/Welding	
	Lowering/Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Dormant			
								Yes	No	N/A	
			talled and implemented plan and stormwater		cordance with the appr gement plans?	roved	erosion and	$\boxtimes$			
					I in effective operating applicable, manufactur			$\boxtimes$			
	3. Areas of	offsite	sediment deposition of	bserve	d?				$\boxtimes$		
Comments: Inspected the following resources: S-RR13, S-RR14, S-006     ECD's were in place at the crossing.  Routine Maintenance: (72-Hour Deadline from Notification)     N/A  Ineffective Controls: (24-Hour Deadline from Notification)     N/A  Recommended Corrective Action: N/A  Deadline: N/A  The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.  Inspector Signature:											
	inspector Sig	natul	E / 500	~\ <u>rve.</u>							

Date: Wednesday, October 28, 2020



## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

Date: Wednesday, October 28, 2020

<u>Figure 1</u>: Designated stream crossing S-RR13, ECD's are in place.



Figure 2: Designated stream crossing S-RR14, ECD's are in place.



Figure 3: Designated stream crossing S-006, ECD's are in place.



- <u>Figure 4</u>: Near MP 219.5 area is stabilized and ECD's are in place.

