

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 21, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11669+00 – 11788+43	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S- MN21, S-MN22, S-EF65, S-EF62, S-IJ42 and W-IJ46-PEM.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, October 21, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 21, 2020

Figure 1: STA 11670+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 164°S (T) ● 37°18'11"N, 80°23'37"W ±16ft ▲ 2793ft



11670

Figure 2: STA 11695+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 166°S (T) ● 37°17'55"N, 80°23'19"W ±16ft ▲ 2524ft



11695

Figure 1: Stream S-MN22 – Controls in place and functioning properly around stream S-MN22 crossing.

☉ 87°E (T) ● 37°17'50"N, 80°23'12"W ±98ft ▲ 2426ft



S-MN22

Figure 1: STA 11755+00 – Controls in place and functioning properly.

☉ 86°E (T) ● 37°17'48"N, 80°22'16"W ±32ft ▲ 2137ft



11755