

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, December 8, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	STA 10929+38 – 11023+80 ATWS 1145/1146/974/467/1331 MVP-GI-244	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ19, S-IJ18, S-RR5, S-E24, S-E25 and S-Y2.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Tuesday, December 8, 2020

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, December 8, 2020

**Figure 1: STA 11019+00** – Controls in place functioning properly.

☉ 256°W (T) ● 37°19'24"N, 80°33'16"W ±1791ft ▲ 2457ft



**Figure 2: STA 10988+00** – Controls in place functioning properly.

☉ 300°NW (T) ● 37°19'31"N, 80°33'51"W ±32ft ▲ 2379ft



**Figure 3: STA 10970+00** – Controls in place functioning properly.

☉ 308°NW (T) ● 37°19'32"N, 80°33'54"W ±14646ft ▲ 2379ft



**Figure 4: STA 10941+00** – Controls in place functioning properly.

☉ 113°E (T) ● 37°19'47"N, 80°34'46"W ±16ft ▲ 2253ft

