

FIELD INSPECTION REPORT

| | | | |
|--|--|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Wednesday, December 2, 2020 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread G: Montgomery County | STA 11788+43 – 11900+00 MVP-MN-266.03 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Wednesday, December 2, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 2, 2020

Figure 1: STA 11899+00 – Controls in place functioning properly.

☉ 265°W (T) ● 37°15'7"N, 80°24'4"W ±4639ft ▲ 2117ft



11899

Figure 2: STA 11856+00 – Controls in place functioning properly.

☉ 338°N (T) ● 37°17'9"N, 80°20'53"W ±98ft ▲ 2183ft



Figure 3: STA 11835+00 – Controls in place functioning properly.

☉ 6°N (T) ● 37°17'28"N, 80°21'2"W ±16ft ▲ 2240ft



Figure 4: STA 11806+00 – Controls in place functioning properly.

☉ 253°W (T) ● 37°17'11"N, 80°22'25"W ±14954ft ▲ 2205ft



11806