

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 24, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County Craig County	MVP-GI-256 STA 11353+21 – 11525+00 MVP-CR-258.01/258.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-PP4, S-PP3, S-PP1, S-OO13, S-OO14, W-CD12 and S-KL43.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, February 24, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 24, 2021

Figure 1: STA 11456+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 265°W (T) **LAT:** 37.319496 **LON:** -80.439435 ±16ft **ALT:** 2230ft



Figure 2: STA 11396+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 272°W (T) **LAT:** 37.313256 **LON:** -80.469599 ±16424ft **ALT:** 2326ft



Figure 3: STA 11526+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 70°E (T) **LAT:** 37.329474 **LON:** -80.420548 ±16ft **ALT:** 2256ft



Figure 4: STA 11494+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 259°W (T) **LAT:** 37.325201 **LON:** -80.429850 ±32ft **ALT:** 2207ft

