

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, February 5, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	Laydown Yard 026 Laydown Yard 028 Laydown Yard 029	<b>Weather:</b>	Snow

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Friday, February 5, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, February 5, 2021

**Figure 1: Laydown Yard 026** – Controls in place and functioning properly around fueling station.

**BRG:** 161°S (T) **LAT:** 37.318733 **LON:** -80.657545 ±16ft **ALT:** 1786ft



**Figure 2: Laydown Yard 026** – Secondary containment in place and functioning properly.

**BRG:** 288°W (T) **LAT:** 37.318037 **LON:** -80.656706 ±98ft **ALT:** 1769ft



**Figure 3: Laydown Yard 028** – Controls in place and functioning properly.

**BRG:** 200°S (T) **LAT:** 37.336107 **LON:** -80.808359 ±16ft **ALT:** 1535ft



LY 028

**Figure 4: Laydown Yard 029** – Controls in place and functioning properly.

**BRG:** 264°W (T) **LAT:** 37.362355 **LON:** -80.677207 ±98ft **ALT:** 1710ft



LY 029