

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, July 23, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	Laydown Yard 029 MVP-GI-238/241.01/241.04 ATWS 339A/340/1390/1391	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: P-S1, S-G33 and S-G31.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, July 23, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 23, 2020

Figure 1: LY 029 – Controls in place and functioning properly.

☉ 268°W (T) ● 37°21'44"N, 80°40'38"W ±541ft ▲ 1712ft



029

Figure 2: STA 10697+00 – Controls in place and functioning properly.

☉ 105°E (T) ● 37°20'57"N, 80°39'8"W ±16ft ▲ 2045ft



10697+05

Figure 3: Stream S-G32 – Controls in place and functioning properly around S-G32 stream crossing.

☉ 141°SE (T) ● 37°20'56"N, 80°39'7"W ±16ft ▲ 2054ft



S-G32

Figure 4: STA 10711+00 – Controls in place and functioning properly.

☉ 111°E (T) ● 37°20'55"N, 80°38'51"W ±32ft ▲ 2318ft



10711