

FIELD INSPECTION REPORT

| | | | |
|-----------------------------------|--|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Thursday, June 11, 2020 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread G: Giles County | STA 11353+67 – 11471+52 MVP-GI-256 MVP-CR-258.01 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-SS8, S-CD8, S-AB8, S-DD3, S-G16, S-G15 and S-G13.

Ineffective Controls: *(24-Hour Deadline from Notification)*

- STA 11428+00: P1 repair needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, June 11, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, June 11, 2020

Figure 1: STA 11463+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 65°NE (T) ● 37°19'27"N, 80°27'48"W ±8035ft ▲ 2240ft



11463

Figure 2: Stream S-0014 – Controls in place and functioning properly. Area stabilized with straw.

☉ 220°SW (T) ● 37°19'7"N, 80°26'28"W ±16ft ▲ 2138ft



S-0014

Figure 3: STA 11428+00 – P1 repair needed.

☉ 330°NW (T) ● 37°18'55"N, 80°26'50"W ±16ft ▲ 2258ft



P1 repair

11428

Figure 4: STA 11414+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 215°SW (T) ● 37°18'46"N, 80°27'4"W ±32ft ▲ 2319ft



11414