

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 6, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County Giles County	STA 11596+94 - 11618+91 STA 11204+61 - 11246+69 MVP-MN-258.03/258.04/MLV-AR-25 ATWS 1373/1057/1370/1370A/1347	Weather (Wet/Dry/Rain):	Dry

OTAGE OF CONCEDUCTION. (Observed)				
STAGE OF CONSTRUCTION: (Check all that apply)				
Clearing Rough Grading Trench Exca	avation Pipe Assembly, Testing & Installation			
☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilizat	tion Other: Dormant			
	Yes No N/A			
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?				
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?				
3 Areas of offsite sediment deposition were observed?				
Comments: Inspected the following resources: S-OO6, S-RR14 and S-RR13.				
Recommended Corrective Action: N/A				

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Date: 01/06/2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 6, 2020

Fig. 1: **Stream S-RR13** – Controls in place and functioning properly.



Fig. 2: **Stream S-OO6** – Controls in place and functioning properly.



Fig. 3: **STA 11600+00** – Craig's Creek Road crossing controls in place and functioning properly.



Fig. 4: **STA 11231+00** – Controls in place and functioning properly. Area stabilized with straw and vegetation.

