

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, January 15, 2020	Project Contact:	Brian Clauto
Spread: Montgomery County MP 221- 222.6 AR MLV 26	Spread G	Weather (Wet/Dry/Rain):	Wet
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other: <u>Dormant</u>
		Yes No N/A	
Are controls installed and implemented in accordance with the approved □□□ crosion and sediment control plan and stormwater management plans?			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
3 Areas of offsite sedi	iment deposition were observed?		
Comments: Inspected designated streams and wetlands included: S-MN 21, S-MN 22, S- EF 65, S-EF62, S-IJ 52 ECD's were in place and functioning at the designated crossings. St 11703+79 waterbar end treatment is showing signs of being bypassed Deadline: 24 hrs. from notification St11703+79 silt fence in 2 locations has been undermined Deadline: Routine Maintenance 72 hours from notification Recommend Corrective Action: Maintain all controls per the approved plan.			
Deadline: See above The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.			

Inspector Signature: ____ Date: <u>2-3-2020</u>




FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, January 15, 2020

 Fig. 1. St11703+79 waterbar end treatment is showing signs of being bypassed



Fig. 2. St 11703+79 silt fence in has been undermined



• Fig. 3. St 11703+79 silt fence in has been undermined



Fig. 4. Designated crossing S-MN22, ECD waddles in place

