

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, February 4, 2020	Project Contact:	Brian Clauto
Spread G: Craig Giles	AR GI 244 ATWS 1144, 1143, 1146, 1145 MP 208.4- 209.1 AR- 258.02 MP 218.5-218.5 AR-258.03 ATWS 1057, 1373 MP 219.5-219.8	Weather:	Dry
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)			
☐ Tree Felling	☐ Clearing/Grubbing ☐ Gra	ding	ning Stringing/Welding
☐ Lowering/Backfilling	☐ Final Grading ☐ Ten	np. Stabilization Perm.	Stabilization Dormant
			Yes No N/A
	rols installed and implemented in accorda t control plan and stormwater manageme		and 🖂 🗆
	ontrol measures properly maintained in ef d engineering practices and, where applic		
3. Areas of	offsite sediment deposition observed?		
 Comments: Inspected the following resources: S-IJ 8, S-IJ9, S-RR5, S-QQ2, S-RR13, S-RR14, S-006 Routine Maintenance: (72-Hour Deadline from Notification) N/A Ineffective Controls: (24-Hour Deadline from Notification) - On AR 258.02, the ECD waddle required repair on the bridge Recommended Corrective Action: Maintain and install all controls per the approved PSS&S. 			

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, February 4, 2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Tuesday, February 4, 2020

Figure 1: Above designated stream S-RR5, ECD's are in place.

South East Elevation



Figure 3: At designated crossing S-QQ2 on AR 258.02 the ECD required maintenance.



Figure 2: At St11016+79 ECD's are in place

Figure 4: At designated crossing S-006, ECD's are in place.



