

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, June 5, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11471+50 – 11525+00 STA 11600+00 – 11620+00 MVP-CR-258.02/258.01 MVP-MN-258.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-PP4, S-PP3, S-PP1, S-PP2, S-OO6, S-RR14 and S-RR13.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, June 5, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, June 5, 2020

Figure 1: STA 11525+00 – Controls in place and functioning properly. Area stabilized with straw and vegetation.

☉ 232°SW (T) ● 37°19'43"N, 80°25'18"W ±16ft ▲ 2278ft



Figure 2: STA 11498+00 – Controls in place and functioning properly. Area stabilized with straw and vegetation.

☉ 59°NE (T) ● 37°19'32"N, 80°25'38"W ±98ft ▲ 2256ft



Figure 3: STA 11616+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 58°NE (T) ● 37°18'47"N, 80°24'8"W ±4445ft ▲ 1912ft



Figure 4: Stream S-006 – Controls in place and functioning properly around Craig Creek crossing.

☉ 258°W (T) ● 37°18'48"N, 80°24'15"W ±16ft ▲ 1944ft

