

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, April 22, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13674+00 – 13690+00	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to a complaint (IR#: 294773) received on April 21, 2020 for the Grassy Hill Road area near Teals Creek.

1. The complaint describes “ongoing flooding, stream bank erosion and sedimentation into Teals Creek” along the MVP ROW.

Observations:

1. No evidence of sediment discharge into Teals Creek (S-E28) or unnamed tributary (S-E29).
2. No controls in need of maintenance were found during the inspection.
3. All controls were installed and functioning properly at the time of inspection.
4. ROW experiences periodic flooding from Teals Creek during bank-full events.
5. Banks of Teals Creek in this area are incised and frequently fail as the stream naturally meanders within the flood plain.

Comments: ROW inspected in Franklin County from STA 13674+00 though STA 13690+00.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, April 22, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 22, 2020

Figure 1: STA 13687+50 – Controls in place and functioning properly. ROW stabilized with temporary vegetation and timber matting in travel lane.

⊗ 308°NW (T) ● 37°5'10"N, 79°56'55"W ±16ft ▲ 1140ft



Figure 2: Stream S-E29 – Unnamed trib. to Teels Creek. Controls in place and functioning properly at crossing.

⊗ 293°NW (T) ● 37°5'24"N, 79°56'56"W ±246ft ▲ 1175ft



Figure 3: Stream S-E29 – Unnamed trib. to Teels Creek crossing looking downstream towards Teels Creek confluence. Incised stream banks covered in stabilization matting within ROW.

⊗ 226°SW (T) ● 37°5'18"N, 79°57'0"W ±16ft ▲ 1157ft



Figure 4: STA 13678+00 – Recent P1 repair along Teels Creek (S-E28). Note incised stream banks caused by stream meandering along inside bends.

⊗ 297°NW (T) ● 37°5'18"N, 79°57'2"W ±16ft ▲ 1153ft

