

COMPLAINT INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon	
Inspection Date:	Thursday, August 9, 2018	Project Contact:	Brian Clauto, Tim Bowen	
Spread:	Spread G	Weather (Wet/Dry/Rain):	Dry	
STAGE OF CONSTRUCTION: (Check all that apply)				
TAGE OF CONSTRUCTION. (Check all that apply)				

STAGE OF CONSTRUCTION: (Check all that apply)			
☐ Clearing ☐ Rough Grading ☐ Trench Excav	vation Pipe Assembly, Testing & Installation		
☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilizatio	on Other:		
	Yes No N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
3 Areas of offsite sediment deposition were observed?			
Comments: This report is for an inspection at an area Giles County, east of Doe Creek Farm and south and west of Mountain Lake Road at about MP 207.75, in response to a complaint of sediment-laden water running off the ROW and into streams at stream crossings S-E24 and S-E25. 1. E&S controls appeared in good condition. 2. Stabilization applied to streambank next to timber bridge at S-E25. 3. Stream channels appeared in good condition. Sediment deposits not evident and water in channels flowing clear.			
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this reproductive non-compliance and/or corrective actions are not completed by the deadline, other ensuring compliance on the above project.			



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Thursday, August 9, 2018



E&S controls in good condition.



Stabilization applied to streambank.



Sediment deposits not evident in channel. Water flowing clear.

Comment 4.