



	-		
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, March 8, 2021	Project Contact:	Brian Clauto
Spread G: Giles	ST11290+00-11353+99 ATWS 633, 633A, 1147 AR-GI256.02	Weather:	Dry

Giles	Α	TWS	633, 633A, 1147 256.02		Weather:		Dry					
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling			Clearing/Grubbing		Grading	☐ Trend	ching		Strin	nging/Welding		
☐ Lowering/Bac	kfilling		Final Grading		Temp. Stabilization	☐ Perm	ı. Stabilization	\boxtimes	Dorr	mant		
								Yes	No	N/A		
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes					
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes					
3. Ar	Areas of offsite sediment deposition observed?								\boxtimes			
 <u>Comments:</u> Inspected the following resources: W-MM10, S-MM18, S-NN13, S-NN14, S-NN11 ECD's were in place and functioning at the designated crossings. Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) N/A 												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												
										J		

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, March 8, 2021

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline <u>Date</u>: Monday, March 8, 2021

Figure 1: At MP213.8 areas have recently been re stabilized with mulch.



Figure 2: Near St11310+00 the area has recently been re stabilized with mulch.



 <u>Figure 3</u>: Near St11320+00 the area has recently been re stabilized with mulch.



 Figure 4: Above designated stream crossing S-NN12, ECD's and stabilization in place.

