

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, December 26, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Montgomery County</b>	STA 11669+08 – 11788+43 MLV-MN-AR-26	<b>Weather (Wet/Dry/Rain):</b>	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-MN21, S-MN22, S-EF65, S-EF62, S-IJ52 and W-IJ46.

- STA 11687+00: P1 maintenance needed at S-MN21 bridge.
- STA 11740+00: P1 maintenance needed at S-EF65 bridge.
- STA 11744+00: P1 maintenance needed at S-EF62 bridge.

**Recommended Corrective Action:** Maintain and install all controls per the approved plans and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 12/26/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, December 26, 2019

<p>Fig. 1: <b>STA 11687+00</b> – P1 maintenance needed.</p> <p style="font-size: small; margin-bottom: 0;"> <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">⊗</span> 280°W (T)             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">●</span> 37°17'58"N, 80°23'28"W ±16.4ft             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">▲</span> 2453ft         </p>  <p style="font-size: x-small; text-align: right; margin-top: 0;">S-MN21</p>	<p>Fig. 2: <b>STA 11687+00</b> – P1 maintenance needed.</p> <p style="font-size: small; margin-bottom: 0;"> <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">⊗</span> 130°SE (T)             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">●</span> 37°17'58"N, 80°23'27"W ±16.4ft             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">▲</span> 2452ft         </p>  <p style="font-size: x-small; text-align: right; margin-top: 0;">S-MN21</p>
<p>Fig. 3: <b>STA 11740+00</b> – P1 maintenance needed.</p> <p style="font-size: small; margin-bottom: 0;"> <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">⊗</span> 250°W (T)             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">●</span> 37°17'44"N, 80°22'34"W ±16.4ft             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">▲</span> 2007ft         </p>  <p style="font-size: x-small; text-align: right; margin-top: 0;">SEF66</p>	<p>Fig. 4: <b>STA 11744+00</b> – P1 maintenance needed.</p> <p style="font-size: small; margin-bottom: 0;"> <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">⊗</span> 75°E (T)             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">●</span> 37°17'47"N, 80°22'30"W ±16.4ft             <span style="display: inline-block; width: 15px; height: 15px; border: 1px solid black; border-radius: 50%; text-align: center; line-height: 15px;">▲</span> 2012ft         </p>  <p style="font-size: x-small; text-align: right; margin-top: 0;">11744</p>