

Complaint Investigation

			1	
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant	
Inspection Date:	Wednesday, December 11, 2019	Project Contact:	Brian Clauto	
Spread: Giles Co. AR GI 234 AR GI 241.01 ATWS1331,1333,1332 ,1360 MP 202.4 MP 206.8	Spread G	Weather (Wet/Dry/Rain):	Dry	
STAGE OF CONSTRUCTION: (Check all that apply)				
_	Clearing			
Backfilling and Grade	e Restoration	3 & Stabilization	Other: <u>Dormant</u>	
Are all control meas condition in accorda applicable, manufac Areas of offsite sedi	d and implemented in accordance with the nt control plan and stormwater managementers properly maintained in effective opeince with good engineering practices and sturer specifications? ment deposition were observed?	nent plans? erating		
 Comments: Inspected designated stream included: S-Q14, S-G32, S-E20, S-Y2, S-Y3, S-A32 ECD's controls were in place and functioning at crossings. Access Roads inspected included GI 234, ditch line has recently been re blanketed and is stable. Recommend Corrective Action: N/A 				

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

	Patthesta	
Inspector Signature:	1 to rest in	Date: 12-30-19



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, December 11, 2019

Fig. 1 Designated stream crossing S-G32, ECD's in place and functioning.



Fig. 2 Designated stream crossing S-E20, ECD's in place and functioning.



 Fig. 3 Designated stream crossing S-Y3, ECD's in place and functioning.




Fig. 4. Designated stream crossing S-A32, ECD's in place and functioning.

