

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, October 8, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Giles County</b> <b>MLV26</b> <b>GI 256.02</b> <b>ATWS 1370</b> <b>MLV 249.02</b> <b>GI 249.01</b> <b>ATWS 1331</b>	<b>Spread G</b>	<b>Weather (Wet/Dry/Rain):</b>	<b>Rainy</b>

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant/ winter stabilization

- |   |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?                                                                                                                             | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- Inspected designated streams included: S-N11, S-NN14, S-NN13, S-NN12, S-Y2, S-Y3
- ECD's were in place at designated streams and no impacts were observed.

**Recommend Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-15-19

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, October 8, 2019

- Fig. 1 Designated stream S-N11, ECD's are in place and functioning.



- Fig. 2 Near MP 214.4 stabilization has been applied and ECD's are in place and functioning.



- Fig. 3 Designated stream S-Y2, ECD's are in place and functioning.



- Fig. 4 Designated stream S-N12, ECD's are in place and functioning.

