

## **FIELD INSPECTION**

| Project Name:  | Mountain Valley Pipeline  | Inspector:              | Matthew Grant                         |
|--|---|-------------------------|---------------------------------------|
| Inspection Date:   | Tuesday, September 17, 2019   | Project Contact:        | Brian Clauto                          |
| Spread: Montgomery<br>County<br>AR256<br>MP215-217<br>Giles County<br>MP218-218.2  | Spread G  | Weather (Wet/Dry/Rain): | Dry                                   |
| STAGE OF CONSTRUCTION: (Check all that apply)  |   |                         |                                       |
| Clearing   | Rough Grading   | Trench Excavation       | Pipe Assembly, Testing & Installation |
| Backfilling and Grade  | e Restoration Final Grading   | & Stabilization         | Other: Dormant/ winter stabilization  |
|  |   |                         |                                       |
|  |   | Yes No N/A              |                                       |
|  | d and implemented in accordance with the<br>nt control plan and stormwater management |                         |                                       |
| Are all control measures properly maintained in effective opera condition in accordance with good engineering practices and, v applicable, manufacturer specifications?  |   |                         |                                       |
| 3 Areas of offsite sediment deposition were observed?  |   |                         |                                       |
| Comments: Inspected designated streams included: SKL-43,S-0014, S-0013, S-0012, S-PP1, S-PP3 ECD's inspected were in place at designated stream crossings. St11520+00 sump requires maintenance  Recommend Corrective Action: Maintain and install all controls per the approved plan and specs  |   |                         |                                       |
| Deadline: Within 24hr notification  The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. |   |                         |                                       |



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Tuesday, September 17, 2019

Fig. 1 St 11520+00 sump requires maintenance



Fig. 2 Near ST11354+00 area has been stabilized with seed and mulch



 Fig. 3 Near MP 216.3 holes protected per DCR Will Orndorff.




Fig. 4 Near St11524 stabilization has been applied by helicopter near the base Sinking Creek Mountain.

