

## **FIELD INSPECTION**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, August 29, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11023+80 - 11064+53 MVP-GI-244 MVP-GI-241.04	Weather (Wet/Dry/Rain):	Dry

MVP-GI-241.04					
STAGE OF CONSTRUCTION: (Check all that apply)					
Clearing Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation			
Backfilling and Grade Restoration Fir	nal Grading & Stabilization	Other: Dormant			
	Yes No N	//A			
Are controls installed and implemented in accordate erosion and sediment control plan and stormwater					
Are all control measures properly maintained in ef condition in accordance with good engineering prapplicable, manufacturer specifications?					
3 Areas of offsite sediment deposition were observe	od? □ ⊠ □				
Comments: Inspected the following resources: S-IJ19	, S-IJ18, and S-IJ16B.				
STA 11051+30: Maintain sump. STA 11055+00: Maintain P1.					
Recommended Corrective Action: Install and maintain all controls per the approved plans and PSS&S.					
<b>Deadline:</b> Within 24-hr notification					
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for experience on the above project.					

Date: <u>08/29/2019</u>



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Thursday, August 29, 2019

Fig. 1: **STA 11023+00** – Controls in place. Area stabilized with vegetation.



Fig. 2: **Stream S-IJ16B** – Controls in place. Area stabilized with vegetation.



Fig. 3: STA 11051+30 – Sump needs maintenance.



Fig. 4: **STA 11055+00** – P1 needs maintenance.

