

FIELD INSPECTION

FIELD INSPECTION			
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, October 24, 2018	Project Contact:	Brian Clauto
Spread: Giles County MP209 St#11064- 11073 MP 217 St#11489 Montgomery County MP219 St#11600- 11613	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other:
 erosion and sedime Are all control meas condition in accorda applicable, manufac 	d and implemented in accordance with the nt control plan and stormwater managementers properly maintained in effective operance with good engineering practices and sturer specifications? ment deposition were observed?	ent plans? rating	
 Area 1 –MP 217 St#11487 the clean water diversion is inadequate, this issue has been noted in the SWPPP for corrective action. Area 2- MP 209 St#11064+84-11703+00 is not adequately stabilized. Area 3- MP219 St#11600-11613 have been adequately mulched. Recommended Corrective Action: Maintain and install all controls per the annual standard and specs.			
Deadline: Within 24hr notification The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.			

Inspector Signature:___



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, October 24, 2018



Fig. 2 St#11064+84-11073+00 is not adequately stabilized.




Fig. 3 St#11064+84-11073+00 is not adequately stabilized.



