

# **FIELD INSPECTION**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, June 3, 2019	Project Contact:	Brian Clauto
Spread G: Montgomery County	STA 11789+00 - 11902+00	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)				
Clearing Rough Grading Trench Exca	vation Pipe Assembly, Testing & Installation			
☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilizati	on Other: Dormant			
	Yes No N/A			
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?				
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?				
3 Areas of offsite sediment deposition were observed?				
STA 11829+50: Sediment off ROW STA 11834+00 to 11836+00: SSF undermined. STA 11836+00: Sediment off ROW. STA 11837+00: Maintain/repair SSF. STA 11850+00: Sediment off ROW. STA 11850+00: Maintain/repair P1. STA 11870+00: Sediment off ROW. STA 11889+00: Sediment off ROW. STA 11889+00: Maintain CFS and stabilize erosion. STA 11901+00: Maintain CFS.  Recommended Corrective Action: Maintain and install all control	s per the approved plans and PSS&S.			

### **Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Date: 06/03/2019



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, June 3, 2019

Fig. 1: **STA 11829+00** – Sediment off ROW. Fig. 2: **STA 11834+00 – 11836+00** – SSF undermined. Fig. 3: **STA 11836+00** – Sediment off ROW. Fig. 4: STA 11837+00 - Maintain/cleanout SSF. @ 93°E (T) @ 37°17'27"N, 80°20'59"W ±16.4ft ▲ 2203ft 



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, June 3, 2019

Fig. 5: **STA 11850+00** – P1 undermined. Fig. 6: **STA 11850+00** – Sediment off ROW. Fig. 7: STA 11901+00 - Maintain/cleanout CFS. Fig. 8: STA 11889+00 - Maintain/cleanout CFS. ₱ 51°NE (T) ● 37°17'15"N, 80°20'16"W ±16.4ft ▲ 2191ft



# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, June 3, 2019

