

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant	
Inspection Date:	Tuesday, June 11, 2019	Project Contact:	Brian Clauto	
Spread: Montgomery County AR266	Spread G	Weather (Wet/Dry/Rain):	Dry	
STAGE OF CONSTRUCTION: (Check all that apply)				
Clearing	Rough Grading	Trench Excavation	☐ Pipe Assembly, Testing & Installation	
Backfilling and Grade	e Restoration Final Grading	& Stabilization	Other: Dormant	
		Yes No N/A		
	d and implemented in accordance with the nt control plan and stormwater management			
Are all control meas condition in accorda applicable, manufac	ures properly maintained in effective oper nce with good engineering practices and, turer specifications?	rating 🗵 🗆 🗆 where		
3 Areas of offsite sedi	ment deposition were observed?			
Comments: AR 266 is showing signs of erosion Recommended Corrective Action: Repair AR per the annual standard and specs.				
Deadline: _Within 24hr r	notification			
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.				

Inspector Signature:___



FIELD INSPECTION PHOTO LOG

Project Name: <u>Mountain Valley Pipeline</u> Date:Tuesday, June 11, 2019

Fig. 1. AR 266 showing signs of erosion	
South West Elevation © 65°NE (T) ● 37°16′10″N, 80°19′21″W ±16.4ft ▲ 1691ft	