

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, May 8, 2019	Project Contact:	Brian Clauto
Spread: Craig County MP217 AR258.01	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	Restoration Final Grading	& Stabilization	Other: Dormant
		Yes No N/A	
	d and implemented in accordance with the nt control plan and stormwater management		
	ures properly maintained in effective oper nce with good engineering practices and, turer specifications?		
3 Areas of offsite sedi	ment deposition were observed?		
Comments: Streams inspected included: S-PP1, S-0012, S-0013. ECD's were in place at all streams inspected and no impacts were observed.			
Recommended Corrective Action: N/A			
Deadline: _N/A			
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.			

Inspector Signature:___



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, May 8, 2019

Fig. 1 Designated stream SPP-1 ECD's are in place and functioning.



 Fig. 3 Above designated streams S-0012 and S-0013, ECD's in place.



Fig. 2 St#11478+00 two-tone areas have been blanket matted.



Fig. 4 Access road 258.01 controls in place and functioning.

