

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, April 18, 2019	Project Contact:	Brian Clauto
Spread: Craig County AR GI 258.02 MP 218 St#11254-11473	Spread G	Weather (Wet/Dry/Rain):	Dry
Clearing Backfilling and Grade Are controls installe erosion and sedime Are all control meas condition in accorda applicable, manufac		ent plans? rating	☐ Pipe Assembly, Testing & Installation ☐ Other: Dormant
Comments: Streams inspected included: S-PP4, S-PP3 St#11517+81 water bar conveyance is eroding St#11511+00 two tone area is eroding and requires repair / stabilization St#11489 clean water diversion inlet has eroded St#11473 two tone area is eroding and requires repair / stabilization Recommended Corrective Action: Maintain all controls per the approved plan and specs.			

Deadline: Within 24hr notification.

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ____ Date: _5-6-19



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Thursday, April 18, 2019

Fig. 1 St#11517+81 water bar conveyance is eroding



Fig. 2 St#11511+00 two tone area is eroding and requires repair / stabilization



Fig. 3 St#11489 clean water diversion inlet has eroded



 Fig. 4 St#11473 two tone area is eroding and requires repair / stabilization

