

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, April 9, 2019	Project Contact:	Brian Clauto
Spread: Giles County MP202 St#10697+00 MP219 St#11600+13- 11607+34 GI-234 GI-240 GI-241.01	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCT	ION: (Check all that apply)		
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other: Dormant
		Yes No N/A	
	d and implemented in accordance with th nt control plan and stormwater managem		
2 condition in accorda	sures properly maintained in effective ope ance with good engineering practices and cturer specifications?		
3 Areas of offsite sedi	ment deposition were observed?		
Comments: Streams inspected included: S-G32, S-A32, S-006 ECD's and stabilization are functioning between St#11600+13-11607+34 Access Rd GI-234 matting has slipped on conveyance channel slope and requires re-install. Recommended Corrective Action: Maintain all controls per the approved plan and specs.			
<u>Deadline:</u> Within 24hr notification.			
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.			
Inspector Signature:	Pattine Hand _ D	ate: _4/22/19 _	



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Tuesday, April 9, 2019

 Fig. 1 Access Rd GI-234 matting has slipped off channel slope.



Fig. 2 Designated stream S-G32, ECD's in place



Fig. 3 Designated stream S-A32, ECD's in place



Fig. 4 Designated stream S-006, ECD's in place

