

FIELD INSPECTION

FIELD INSPECTION			
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, March 12, 2019	Project Contact:	Brian Clauto
Spread: Giles County MP214 St#11330-11322 Montgomery County MP221-222 11670-11743	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other: Dormant
 arosion and sediment Are all control meas condition in accordat applicable, manufact 	d and implemented in accordance with the nt control plan and stormwater managemeures properly maintained in effective opernce with good engineering practices and, sturer specifications? ment deposition were observed?	ent plans? rating	
Comments: Streams / wetlands inspected included: S-MN21, S-MN22, S-EF65, S-NN12, GH7, S-GH15, S-GH14 St#11675+30 P1 fence is undermined St#11677+50 sump triple stack is undermined St#11679+40 sump triple stack is undermined St#11686+81 SS fence is undermined Recommended Corrective Action: Maintain all controls per the approved plan.			
Deadline: _Within 24hr notification			

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Date: 3-21-19



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Tuesday, March 12, 2019

Fig. 1 St#11675+30 P1 fence is undermined



Fig. 2 St#11677+50 sump triple stack is undermined



Fig. 3 St#11679+40 sump triple stack is undermined



Fig. 4 St#11686+81 SS fence is undermined

