

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:				M	Matthew Grant		
Inspection Date:	Wednesday, March 6, 2019	Project Contact:				Bı	ian Clauto		
Spread: Giles County MP216-MP215 St#11451-11361	Spread G	Weather (Wet/Dry/Rain):			Rain):	Di	у		
STAGE OF CONSTRUCT	ION: (Check all that apply)								
Clearing	Rough Grading Trench Excavation						Pipe Assembly, Testing & Installation		
Backfilling and Grade	e Restoration	& Stabilization	on			\boxtimes	Other: Dormant		
	d and implemented in accordance with the nt control plan and stormwater management		Yes ⊠	No	N/A				
Are all control meas condition in accorda applicable, manufac									
3 Areas of offsite sedi	ment deposition were observed?			\boxtimes					
St#1421+50 sumSt#11361+75 surSt#11361+00 surSt#11428+00 sm	ds inspected included: S-0013, S-0 p end treatment is undermined np end treatment is undermined np end treatment is undermined all hole, 11427+50 small hole, 114 aper Aden and DEQ personnel W	127+00 soi	il pip	e fe	ature				
Recommended Corrective Action: Maintain all controls per the approved plan.									

<u>Deadline:</u> Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ____ Date: _3-21-19



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, March 6, 2019

Fig. 1 St#11427+00 soil pipe protected by P1 fence



Fig. 2 St#11424+00 small hole feature protected with P1 fence




Fig. 3 St#1421+50 sump end treatment is undermined



Fig. 4 St#11361+00 sump end treatment is undermined

