

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Thursday, February 28, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Giles County</b> AR GI-234 AR GI-249.01 MP 211.6 ST#11172+48--+70 AR GI-249.02 ST#11184+00-11193+85 <b>Craig County</b> MP218 ST#11530+00-11529+50 MP216 ST#11487+00	<b>Spread G</b>	<b>Weather (Wet/Dry/Rain):</b>	<b>Dry</b>

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- Access Rd GI-234 Rodgers Road, ECD's in place and functioning.
- Access Rd GI-249.01 ECD's in place and functioning.
- Access Rd GI-249.02 ECD's in place and functioning
- At St#11529+50 slope has slipped and lacks stabilization.

**Recommended Corrective Action:** Maintain all controls per the approved plan.

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 3-4-19

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 28, 2019

Fig. 1 Access Road GI-234, controls in place.



Fig. 2 ST#11184+00 plunge pool area has been repaired



Fig. 3 At St#11529+50 slope has slipped and lacks stabilization.



Fig. 4 At St#11172+48 P1 control has been repaired.

