

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, March 2, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread G: Giles County</b>	STA 11184+85 – 11227+59 MVP-GI-249.02 MVP-MLV-AR-25	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments: Inspected the following resources: N/A.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_



**Date:** Tuesday, March 2, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, March 2, 2021

**Figure 1: STA 11228+00** – Controls in place and functioning properly. Area stabilized with straw.

**BRG:** 128°SE (T) **LAT:** 37.306140 **LON:** -80.507742 ±25066ft **ALT:** 1799ft



11228

**Figure 2: STA 11210+00** – Controls in place and functioning properly. Area stabilized with straw.

**BRG:** 324°NW (T) **LAT:** 37.302346 **LON:** -80.506252 ±328ft **ALT:** 1908ft



11210

**Figure 3: STA 11195+00** – Controls in place and functioning properly. Area stabilized with straw.

**BRG:** 297°NW (T) **LAT:** 37.306306 **LON:** -80.508496 ±32ft **ALT:** 2081ft



11195

**Figure 4: STA 11180+00** – Controls in place and functioning properly. Area stabilized with straw.

**BRG:** 299°NW (T) **LAT:** 37.308044 **LON:** -80.513361 ±164ft **ALT:** 1892ft



11180