



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Thursday, April 1, 2021	Project Contact:	Brian Clauto		
Spread G: Craig	ST11600-11620 ATWS 1373, 1057 AR 258.04	Weather:	Wet		

AR 258.04												
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling	ee Felling		ubbing [	☐ Gra	iding		Trenching		Stringing/Welding			
☐ Lowering/Backfi	ling $\square$	Final Gradi	ng [	□ Ten	np. Stabilization		Perm. Stabilization	n 🗵 Dormant		mant		
								Yes	No	N/A		
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							$\boxtimes$				
,	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$				
3. Area	<ol> <li>Areas of offsite sediment deposition observed?</li> </ol>								$\boxtimes$			
<ul> <li><u>Comments:</u> Inspected the following resources: S-006, S-RR14, S-RR13</li> <li>ECD's were in place and functioning at the designated crossings.</li> </ul>												
Routine Maintenance: ( <u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: \_\_\_\_\_

Date: Thursday, April 1, 2021



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Thursday, April 1, 2021





Figure 3: Designated crossing S-RR006, ECD's are in place.

