

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, March 18, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11596+94 – 11618+91 STA 11765+00 – 11792+18 MVP-MN-258.05/.04 MVP-MLV-AR-26	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-OO6, S-RR13, S-RR14, W-IJ46-PEM and S-IJ52.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, March 18, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 18, 2021

Figure 1: STA 11615+00 – Controls in place and functioning properly.

BRG: 261°W (T) **LAT:** 37.313524 **LON:** -80.402353 ±2103ft **ALT:** 1891ft



11615

Figure 2: STA 11602+00 – Controls in place and functioning properly.

BRG: 64°NE (T) **LAT:** 37.313360 **LON:** -80.406487 ±16ft **ALT:** 1942ft



11602

Figure 3: STA 11765+00 – Controls in place and functioning properly.

BRG: 277°W (T) **LAT:** 37.296278 **LON:** -80.368033 ±1939ft **ALT:** 2004ft



11765

Figure 4: STA 11792+00 – Controls in place and functioning properly.

BRG: 51°NE (T) **LAT:** 37.297163 **LON:** -80.358847 ±997ft **ALT:** 2145ft



11792